

916 Newton Ave N Pictures



Back of the house



Family room



Dining room



Kitchen



Bathroom



Upstairs




Upstairs



Mechanicals need replacement



Asbestos presumed on water pipes



Hole at soffit



Roofing/decking needs replacement



Garage needs structural review